

Dear Osprey 2 Builders,

"I think I can safely say that the Osprey 2 lines are the most graceful and flowing of any homebuilt amphibian I've ever seen, with the exception of one area, and that is the horizontal stabilizer and elevator tips. Why short change the design with ugly squared off tips? I don't recall any articles pro or con on this in past Newsletters. Also this is just a personal observation, and I could end up being "all wet" on this, pardon the expression! I know the squared tips are perfectly functional, but not a thing of beauty.

If George doesn't object on grounds of aerodynamics, or sonic vibrations, I plan on adding very light rounded tips on my Osprey 2. They probably will be hollowed out balsa, or foam with one layer of fibreglass overlay. I realize the importance of keeping them light."

James D. White Jr.
12619 74th Ave. So.
Seattle, WA 98178

